

Motor 3 Database									
PG=Photographic Copy									
Date	From	Position	At	To	Position	At	Document Type	File	Brief description of contents
12/2/31	E D Randow	RH Fore	Ridgway				Spec sheet		Spec sheet for M3 with photograph. Finished on 12/2/31.
12/28/31	F White	Supt	Ridgway	F C Krauser	Asst to Rec	Denver	PG letter		Put plow & flanger on M3. Handles 5" snow & drifts, Few minor adjustments to M3 & ready to go when M1 fixed on 29th. M3 is the way to go for future motors.
2/26/32	F C Krauser	Purch Agt	Denver	Pioneer Auto Wrecking		Denver	Order		Material for M3. Ship to Odenbaugh, Motor Car Maintainer, Durango.
3/11/32	F White	Supt	Ridgway	Colorado Gear		Denver	Order		Order for 4 roller chain sprockets for M3 per work order 9/2/31.
9/20/32	F White	Supt	Ridgway	F C Krauser	Purch Agt	Denver	Requisition		3 docs to 9/23: 12 spark plugs for M3 & M4.
1/12/33				Kumpf Motor Car		Denver	Voucher		2 docs to 1/12: 12 Five AG amp fuses for M3 & M4.
1/19/33				Hartman Bros		Montrose	Voucher		2 docs to 1/19: Labor fitting piston pins M3.
2/3/33				Hendrie & Bolthoff		Denver	Voucher		2 docs to 2/3: 6 pistons & pins for M3.
6/13/33				P A Pinkerton		Dolores	Voucher		3 docs to 6/13: Blacksmith work repairing broken brake M3.
6/26/33				United Motors		Detroit	Voucher		2 docs to 6/26: 4 Hyatt roller bearings for M3.
6/27/33				M L Foss		Denver	Voucher		2 docs to 6/27: 6 oilers for M3.
11/20/33				Hendrie & Bolthoff		Denver	Voucher		2 docs to 11/20: 12 Victor gaskets for M3.
12/22/33				Hendrie & Bolthoff		Denver	Voucher		2 docs to 12/22: 12 compression rings for M3.
12/31/34	F White	Supt	Ridgway	F C Krauser	Asst to Rec	Denver	PG Telegram		Daily situation report including M3, M4, M5, Ex41/20.
12/30/35	F White	Supt	Ridgway	C W Graebing	Auditor	Denver	Letter		M3 burned out lynite connecting rod 12/27. Cost \$19 each. Odenbaugh wants to replace with steel when next lynite burns out.
3/29/36	O H Steinman	TM	Ridgway	F White		Supt	Ridgway	Telegram	3 docs to 3/30: 3/29 at 14:30 Continental Oil backed into M3 right corner of passenger compartment
1/4/37	F White	Supt	Ridgway		Purch Agt	Ridgway	Requisition		4 steel drive wheels for M3.
1/21/37	F White	Supt	Ridgway		Purch Agt	Denver	Requisition		8 pair connecting rod bearings for Pierce Arrow motors, electrodes & air hose gaskets.
2/5/37	F White	Supt	Ridgway		Purch Agt	Denver	Requisition		6 dozen distributor insulation tips, breaker points & breaker levers for Pierce Arrow 33, oil pump for Pierce Arrow 36. (M3 was a Pierce Arrow 33)
2/23/37	F White	Supt	Ridgway		Purch Agt	Denver	Requisition		8 pair connecting rod bearings for Pierce Arrow 33.
5/18/37	F White	Supt	Ridgway		Purch Agt	Denver	Requisition		3 docs to 5/26: Steel beam for M3.
6/14/37	F White	Supt	Ridgway		Purch Agt	Denver	Requisition		8 lynite Pierce Arrow connecting rods.
8/6/37	F White	Supt	Ridgway		Purch Agt	Denver	Requisition		Set main bearings for M3.
8/18/37	F White	Supt	Ridgway		Purch Agt	Denver	Requisition		Second hand clutch for M3.
8/19/37	F White	Supt	Ridgway		Purch Agt	Denver	Requisition		18 compression rings, 6 oil rings for M3 & some stuff for B&B motor car.
7/20/40	H M Grace	Machinist	Durango	L S Elwel	Foreman	Ridgway	Telegram		Federal inspector here today. M3 needs valve assembly & sand pipe.
11/12/40	R R Boucher	Supt	Durango	R A Coleman	Shop Fore	Ridgway	Telegram		3 docs to 1/15 re hydrostatic test of M3 with ICC inspector.
12/24/40	R A Coleman	Shop Fore	Ridgway	O B Olson	TM	Durango	Telegram		M3 has burnt out bearings. Do you need 2 motors on Xmas? If so need to accrue considerable overtime for shop forces.
4/28/42	R R Boucher	Supt	Durango	R A Coleman	Shop Fore	Ridgway	Telegram		2 docs to 4/30: Put one piece windshield in M3. You can send to Montrose to install.
12/14/42	K M B?		Durango	R A Coleman	Shop Fore	Ridgway	Telegram		3 docs to 12/16: Drive shaft problems. Rivets sheared off left differential housing M3.
1/11/43	R R Boucher	Supt	Durango	R A Coleman	Shop Fore	Ridgway	Telegram		3 docs to 1/18: Trouble getting parts for M3.
Various							Ins Rep		7 inspection reports of M3 1940 to 1945. (Difficult to read).
?									Diagram of front half bearing of M3.